

Document ID# 1714521

Chevrolet SSR

Subject: ASI Resolution - Tonneau Cover (Roof) Does Not Open Evenly or Will Not Open (Install Bushing)
#05-08-67-005A - (10/18/2005)

Models: 2003-2005 Chevrolet SSR - [Built Prior to VIN Breakpoint 4B108184](#)

This bulletin is being revised to add the Delrin Roller Part Number. Please discard Corporate Bulletin Number 05-08-67-005 (Section 08 -- Body and Accessories).

Condition:

Some customers may comment that the roof/tonneau cover does not open evenly or the roof/tonneau cover won't open.

Cause:

The hinge may be sticking on a rubber bushing attached to the hinge. Refer to the illustration.

Correction:

Remove the rubber bushing on the hinge and install a new **delrin** bushing to the hinge.
Parts Information

Part Number Description
15775860 Guide Kit RF Retractable Hinge

